

Jesse Castillo, Interim Chief Business Officer Robert Aldama, Purchasing Manager II

ADDENDUM NO. 1.0

Date: 08/15/2023

Issued by: Sacramento City Unified School District

Project: Project #: 01 48-464

Leataata Floyd ES Telecenter Upgrade Project

This addendum shall supersede the original Informn I ac63 0 T6 (n)ca4 (or)4.en6 (n)cal 6 (hi)2,

them $\overline{}$ All other cond

Part A - Bidding and Contract Requirements

AD 1.10:

Question: Can we change out the Round Clocks to the Message Board clocks? This will save district money as there will only need to be 1 Cat6A pulled to each Clock/Speaker Location, instead of the current requirement for 2. This will also eliminate some additional conduit runs at certain locations to fit additional cables and be more in line with the district's revised standards. Locations with separate clocks & speakers will utilize a cover for the unused location.

Answer:

For this project, the district will accept a combination speaker/message board clock model. At locations where a combination clock/speaker are currently shown on the drawings, contractor shall provide TCC2011B IP module, ACC3011S -US0188 speaker and TCC3011S clock/message board, all installed in ACC3011SBB surface mount backbox. The contractor can also revise number of data drops needed to one per classroom speaker unit in lieu of the two drops needed for the clock and speaker installation as originally show n.

<u>AD 1.11</u>:

Question: Please confirm that the district wants to purchase a TCU3100SW Stream to SIP license for this project. Typically, the district does not use this feature. The TCU3100SW Stream to SIP license allows SIP extensions to be included in paging zones in Telecenter U. This feature provides for audio to be sent to SIP phones or other SIP-enabled devices as part of zones in emergencies, live and prerecorded pages, and bell schedules.

AD 1.12:

Question: Please confirm that the district wants to purchase TCU3300SW Mapping Interface license for this project. Typically, the district does not use this feature. Once configured, the map will display real-time emergency status, call-in location, priority, check-in status, and which locations have audio being actively played. This is best used with call buttons in each classroom for emergency event monitoring and management.

Answer:

This software shall not be required as there are no call stations for initiating status to the mapping interface.

AD 1.13:

<u>Question:</u> Classroom 4 has three additional offices that were identified during the site walk. Please confirm that three additional speaker/message board locations are required for these spaces.

Answer:

Confirmed

AD 1.14:

Question:

AD 1.16:

<u>Question:</u> During the site walk, it was noticed that certain MDF/IDFs may have an adequate number of switch ports and patch panel ports to accommodate for the new CAT 6A drops on this project. Having said that, can the District please clarify the following questions:

- a. If a sufficient number of patch panel ports exist, are contractors permitted to utilize existing patch panels in lieu of providing a new one? This will represent a cost savings to the District.
- b. If a sufficient number of switch ports exist, are contractors permitted to utilize existing switch ports in lieu of providing a new one? This will represent significant cost savings to the District.
- c. If yes to the above, is the District able to advise which MDF/IDFs will require new patch panels and/or switches to help facilitate an apples-to-apples proposal from all bidding contractors?
- d. If not, is it correct to assume that new patch panels and switches will be required for all MDF/IDFs regardless of how many ports are available?

Answer:

Bid/Build per plan . Please provide new data switch and patch panels at IDF locations per plan. The new switch shall be plugged directly into a UPS for dedicated runtime of the intercom system.

AD 1.17:

<u>Question:</u> Please advise if the battery backups shown on the one-line diagrams exist or to be furnished and installed by the contractor. If so, please also advise if a network interface card is required for each of these UPS battery backups to achieve network connectivity (shown below; and the one-line diagrams call for an RJ-45 connection to the battery backup as well). If so, please provide the part number and quantity of network interface cards required.



Answer:

They need to be furnished. 1 per UPS. Part number to be supplied by manufacturer.

Project No: 0148-464

Le

AD 1.22:

<u>Question:</u> Please advise if the contractor is to provide and install (1) or (2) new CAT 6A cables for these new clock/intercom/speaker units.

Answer:

All speaker/message board units are single CAT 6A. The multipurpose room — which will use the larger message board — requires (1) cable each per clock and (1) per message board —.

AD 1.23:

Question: The District has standardized Ortronics modular patch panels (Part #'s OR-SPKSU24 and OR SPKSU48). However, the plans call for (2) 12-port IDC-style patch panels (Part # PHD66U12) per MDF/IDF. To stay consistent, is the District willing to accept a substitution for (1) 24-port or (1) 48-port modular patch panel in lieu of these fixed port patch panels? This setup will allow for the use of color-coded jacks, future expandability, and conserve valuable rack units.

Answer:

Yes.

AD 1.24:

<u>Question:</u> Classroom 4 has three additional offices that were identified during the site walk. Please confirm that three additional speaker/message board locations are required for these spaces.

Answer:

Confirmed

AD 1.25:

<u>Question:</u> Will the District accept a substitution of CAT 6A cabling in lieu of the 2C #18 cabling for the analog clock/speaker units in the plans? It is our understanding that 23 AWG CAT 6A cable will still render the analog units fully functional while maintaining uniformity across the cabling infrastructure.

Answer:

CAT 6a cable shall be used

AD 1.26:

Question: G8c2 286.68 Tm [(t)-2u /TT0 1 T /TT1 1 Tf 12 -0 0 12 116.04 183.48 Tm 72 163.688dvC /P taios4

<u>AD 1.27</u>:

<u>Question:</u> Can the District please advise if EMT conduit is acceptable to install below 8ft? If not, is GRC (Rigid) conduit required for any future conduit pathway installations, regardless of circumstances?

Answer:

EMT acceptable for this campus only.